


簡易裝配便能達到良好的加速效果。

安裝空間小，優化模具結構。


Simple assembly will be able to achieve a good speedup.

Small installation space, optimization of mold structure.



Type	A	B	C	D	E	F	G	H max.	L max.	M	N	P	T	Max. Force
EP.200813	20	8	13.2	25.8	9.4	11.4	6	13.6	5.5	5	15	2.5x10	M3x12	75kg.
EP.251016	25	10	16	32.3	11.8	14.3	7	17	6.8	6	18.5	3x12	M4x16	125kg.
EP.371522	37.5	15	22	48.5	17.7	21.5	10.5	25.5	10.2	8	25	4x16	M6x25	250kg.
EP.502030	50	20	30	64.6	23.6	28.6	14	34	13.6	10	34	5x20	M8x30	500kg.

Example 使用例



2D下載

3D下載

返回索引